

# Final Reclamation Inspection

06/28/2016

Operator: Petro-Canada

Location ID: 311680

Adams County, CO

SESW Section 13 T3S R59W

Aaron Trujillo

Reclamation Specialist

COGCC



**Figure 1:** Photo taken from access road southeast of the location, facing north. Photo shows access road had not been recontoured, vegetation has not achieved 80% to reference. 6' measuring stick for reference.





**Figure 2:** Photo taken from access road southeast of the location, facing south. Photo shows access road had not been recontoured, vegetation has not achieved 80% to reference.





**Figure 3:** Photo taken from access road southeast of the location, facing south. Photo shows access road had not been recontoured, vegetation has not achieved 80% to reference.





**Figure 4:** Photo taken from the southwest corner of the location, facing southeast. Photo shows portion of the reclamation area fenced off.





**Figure 5:** Photo taken from the southwest corner of the location, facing east. Photo shows vegetation over the reclamation area.





**Figure 6:** Photo taken from the southwest corner of the location, facing northeast. Photo shows vegetation over the reclamation area.





**Figure 7:** Photo taken from the southwest corner of the location, facing north. Photo shows vegetation over the reclamation area.





**Figure 8:** Photo taken from the southwest corner of the location, facing west. Photo shows erosion on cut bank. Photo shows location had not been recontoured.





**Figure 9:** Photo taken from the north end of the location, facing north. Photo shows portion of the reclamation area fenced off.





**Figure 10:** Photo taken from the north end of the location, facing west. Photo shows portion of the reclamation area fenced off.





**Figure 11:** Photo taken from the northwest corner of the location, facing south. Photo shows access road had not been recontoured and vegetation has not achieved 80% of reference.





06.28.2016 11:57

**Figure 12:** Photo taken from the northwest corner of the location, facing south. Photo shows erosion on cut bank (right of photo). Photo shows location had not been recontoured.