



**photo 1:** Facing west toward the location. Work underway on recontouring the location.



**photo 2:** Equipment in process of recontouring the location.



**photo 3:** East side of the location facing west.



**photo 4:** South side of the location facing northeast..



**photo 5:** Returned to inspect the work during following week. Location was recontoured and reclamation was being performed.



**photo 6:** A hydro mulch was in the process of being applied at the time of this inspection.



**photo 7:** Facing toward the northwest side of the location.



**photo 8:** Southwest side facing east. The location was drill seeded along the contour.



**photo 9:** Southeast side of the location facing west.



**photo 10:** Northeast side of the location facing southwest.



photo 11: Northeast side of the location facing south.



photo 12: There were excelsior wattles installed at the north perimeter of the location.