



Photo 1. View of project area from the southwestern corner facing center. Interim reclamation has not been conducted. Outer cut and fill slopes are revegetated.



Photo 2. View of the western portion of the project area from the southwestern corner facing northward.





Photo 3. View of the southern portion of the project area from the southwestern corner facing eastward.



Photo 4. View of the northern edge of the project area from the northwestern edge facing eastward.





Photo 5. View of Canada thistle (*Cirsium arvense*) plants in the northern portion of the project area.





Photo 6. View of flowering houndstongue (*Cynoglossum officinale*) in the northern portion of the project area.





Photo 7. View of salt cedar (*Tamarix* sp.) in the northeastern portion of the project area.





Photo 8-11. View of several pieces of trash and debris scattered around well pad area.

June 9, 2016

Inspection Photos 051-06098