



Photo 1. View of the northwestern portion of the project area from the northern corner facing southwestward. Cut and fill slopes are revegetating.



Photo 2. View of the project area from the northern corner facing center. Interim reclamation has not been conducted.





Photo 3. View of the northern portion of the project area from the northern corner facing eastward.





Photo 4. View of the southeastern portion of the project area from the eastern corner facing southwestward.





Photo 5. View of the southwestern corner of the project area. It appears that topsoil is stockpiled here and is revegetating.





Photo 6. View of musk thistles in northern portion of the project area.





Photo 7. View of armoring at culvert along access road. Appears to be in good condition.





Photo 8. View of rock check dams placed along access road. Appear to be functioning at this time, but will soon need maintenance.