

Reference Area Photographs

Inspection Conducted on June 15, 2016

Hunter Ridge Energy Services

Operator #10442

Spill/Release Point ID #446199

6" Transfer Line

Condensate pumped from A27 CDP to M23 Pad

Note: CDP – Centralized Distribution Point

Photos taken by Carlos Lujan



About three Springs in this location, approximately ½ mile north and downgradient of Pipelines crossing the natural drainage (A27 CDP location).



Close-up showing one of the Springs and free-product retained by booms. Natural drainage is dry upgradient of Springs. Continuous flow downgradient. Approximately one mile to stock pond.



Close-up of one of the Springs. Observe sheen coming from the Spring.



Looking upstream (south). Springs are near and on the same side of landslide.



Approximately midway between Springs and stock pond. Looking upstream (south). Observe change of color in vegetation.



Near the stock pond, looking upstream. Stressed vegetation, change of color.



Stream reaching the stock pond. Looking downstream (north). Some free product on vegetation.



Stock pond. Skimming system pumping free-product and impacted water to truck. Gate could not be completely closed. Some flow continues downstream beyond pond.



Skimming activities



Stream channeled to concentrate free-product between yellow tubing. Skimming operation in process.



Downstream of stock pond. Impacted water flows for about 1,500 feet and dries out.



Flow dries out. No stressed vegetation observed beyond this point.