

Final Reclamation Inspection



Photo 1. Photo taken from center of location, facing West. No evidence of disturbance. Uniform, vegetative crop growth throughout location.

Final Reclamation Inspection



Photo 2. Photo taken from center of location, facing North. No evidence of disturbance. Uniform, vegetative crop growth throughout location.

Final Reclamation Inspection



Photo 3. Photo taken from center of location, facing East. No evidence of disturbance. Uniform, vegetative crop growth throughout location.

Final Reclamation Inspection



Photo 4. Photo taken from center of location, facing South. No evidence of disturbance. Uniform, vegetative crop growth throughout location.

Final Reclamation Inspection



Photo 5. Photo taken along access road, east of well location, facing East. A slight growth height difference but above 80% of the reference areas.

Final Reclamation Inspection



Photo 6. Photo taken along access road, east of well location, facing East. Crop height is very similar in height, as shown here.

Final Reclamation Inspection



Photo 7. Reference photo taken north of the midpoint along the access road. Location and access road appears to be reflective of the reference area.