

Final Reclamation Inspection-Sandau East Land Application Area



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo 1. Photo taken from the central irrigation pivot, facing Northeast. Uniform vegetative crop growth throughout location.

Final Reclamation Inspection-Sandau East Land Application Area



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo 2. Photo taken from the central irrigation pivot, facing East. Uniform vegetative crop growth throughout location.

Final Reclamation Inspection-Sandau East Land Application Area



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo 3. Photo taken from the central irrigation pivot, facing Southeast. Uniform vegetative crop growth throughout location.