

Final Reclamation Inspection



Photo 1. Photo taken from location entrance, facing West. Access road has not been reclaimed and equipment (i.e., gate) has not been removed per Rule 1004.

Final Reclamation Inspection



Photo 2. Photo taken from location entrance, facing West. Surface equipment (i.e., culvert) has not been removed per Rule 1004.

Final Reclamation Inspection



Photo 3. Photo taken from location entrance, facing East. Access road has not been reclaimed per Rule 1004.

Final Reclamation Inspection



Photo 4. Photo taken from center of location, facing North. Vegetative growth appears to be reflective of reference areas. Location is currently used for cattle.