



**photo 1:** Facing northwest toward the location.



**photo 2:** Facing northwest along the fill slope of the location.





**photo 3:** Facing southwest toward the location.



**photo 4:** North side of the location facing southeast.





**photo 5:** North side of the location facing southwest.



**photo 6:** North side of the location facing southwest. Diversion ditch is directing stormwater to the north side of the location.





**photo 7:** Facing southwest along the cut slope.



**photo 8:** Facing northwest along the cut slope.