

# Final Reclamation Inspection- Bond Release



**Photo 1.** Photo taken from approximate center of location, facing North. Uniform vegetative growth throughout location. Area appears to be grazed with cattle.



## Final Reclamation Inspection- Bond Release



**Photo 2.** Photo taken from approximate center of location, facing East. Uniform vegetative growth throughout location. Area appears to be grazed with cattle. Debris (i.e., casing) left behind needs to be removed. See following photos.



## Final Reclamation Inspection- Bond Release



**Photo 3.** Photo taken from approximate center of location. Debris (i.e., casing) left behind needs to be removed.



## Final Reclamation Inspection- Bond Release



**Photo 4.** Photo taken from approximate center of location. Debris (i.e., casing) left behind needs to be removed.