

VERTEX ENERGY PARTNERS, LLC FOR  
LONGS PEAK RESOURCES, LLC  
RAIL AY 28-3-1CH  
API #05-123-39863  
NE NW SEC.28-T12N-R66W  
SHL: 180' FWL & 1980' FWL BHL: 310' FSL & 2080' FWL  
LAT: 40.98531 LONG: 104.78359  
WELD COUNTY, COLORADO  
CONTACT NO. 214-534-9569

08.17.2016 09:41



Cirque Resources L.P.  
Railay 28-3-1CH  
N 40.98531 W 104.78359  
NE/NW Sec 28 T12N R66W

Sign Does not reflect current operator

08.17.2016 09:34



Signs do not reflect current operator

08.17.2016 09:35

Emergency contact does not reflect current operator

OIL  
60  
Cirque Resources L.P.  
400 West  
Emergency # 303.226.9503  
HAZARDOUS MATERIALS  
0

OIL  
50  
Cirque Resources L.P.  
400 West  
Emergency # 303.226.9503  
HAZARDOUS MATERIALS  
0

OIL  
40  
Cirque Resources L.P.  
400 West  
Emergency # 303.226.9503  
HAZARDOUS MATERIALS  
0

OIL  
30  
Cirque Resources L.P.  
400 West  
Emergency # 303.226.9503  
HAZARDOUS MATERIALS  
0

08.17.2016 09:36



Oily fluid in open bucket  
Northside of pumpjack

08.17.2016 09:45

A long, dark, perforated pipe lies horizontally across the middle of the frame. The pipe is set against a background of light-colored gravel and sparse green vegetation. To the left, a chain-link fence runs parallel to the pipe. The scene is brightly lit, casting distinct shadows. The text 'Perforated Pipe' is overlaid in black on the right side of the pipe.

Perforated Pipe

08.17.2016 09:45



Stained soil and leak at wellhead

08.17.2016 09:34

Erosion at entrance

08.17.2016 09:40



Erosion south edge of pad

08.17.2016 09:43

Erosion sw corner of pad

08.17.2016 09:44

Erosion west side of location entrance



08.17.2016 09:41

Extent of erosion at sw corner



08.17.2016 09:49

Rilling north cut slope



08.17.2016 09:34

Rilling north cut slope



08.17.2016 09:34

Retention pond over topped east side  
of location entrance

08.17.2016 09:54