



Photo 1. View of cement debris on the well pad.



Photo 2. View of more cement debris on the well pad.



Photo 3. View of more cement debris on the well pad.



Photo 4. View of surface pipeline that does not appear to be in use and needs to be removed.



Photo 5. View of Russian knapweed (*Acroptilon repens*) infestation in the northeastern portion of the project area.