

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/16/2016

Submitted Date:

09/19/2016

Document Number:

685301419**FIELD INSPECTION FORM**Loc ID 326556 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: PO BOX 6501City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hixon, Logan	505-386-8018	logan_hixon@xtoenergy.com	SW EHS Tech
Trobaugh, Robert	505-333-3185	robert_trobaugh@xtoenergy.com	SW Inspection Reports
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Harrison, Lyndon	505-333-3100	lyndon_harrison@xtoenergy.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257076	WELL	PR	07/01/2013	GW	067-08295	HUBER 3-24	PR

General Comment:

Inspection contains corrective action and comment. See Good Housekeeping and Stormwater Sections of report for additional details.
See link at end of report for path to downloadable pictures.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	N side of location has two piles of wood debris and pallets. Similiar issue was noted in previous inspection.		
Corrective Action:	Remove debris to comply with Rule 603.f using the Rule 603.f guidance document for further details.		Date: 10/21/2016

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Safety Rails		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	6' Chain link fence topped with barb wire.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Telemetry Equipment		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			

Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric Motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric Service		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 257076	Type: WELL	API Number: 067-08295	Status: PR	Insp. Status: PR
Producing Well				
Comment:	PR			
Corrective Action:				Date:

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass	Self Inspection	Fail	
Compaction	Fail	Ditches	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Stormwater is running along berm at location entrance and cutting erosion channel as it leaves location. Similiar issue was noted in previous inspection.

Corrective Action: Install or repair required BMPs to comply with Rule 2002.f. Refer to the 1002.f guidance document for further details.

Date: 10/21/2016

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685301429	Wood debris	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3955862
685301431	Wood and pallet debris	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3955863
685301432	Erosion channel at entrance to location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3955864