

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/16/2016

Submitted Date:

09/23/2016

Document Number:

671000445**FIELD INSPECTION FORM**
 Loc ID 433706 Inspector Name: LUJAN, CARLOS On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**General Comment:**

Environmental Inspection conducted after notification from Encana that an unidentified person left a tank valve open. Encana responded to the incident closing the valve and recovering all available produced water. At the time of the inspection, no signs of spill were observed other than wet gravel within the secondary containment. No standing water was observed within the secondary containment. Areas around the tank battery was dry. No odor or staining was observed.

Pieces of liner and netting were observed on the SW section of the pad, mixed in with the soil. Other than that no junk, staining or weeds were observed on site.

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: _____

Comment: A spill fully contained within the secondary containment occurred when an unidentified person left a tank valve open. Spilled water was recovered. No impact, stain, wet soil, etc. was observed around the tank battery. Encana submitted a spill report, doc #401108131 (Spill Point ID #447772).

Corrective Action: Submit a Supplemental Spill report requesting closure.

Date: 09/30/2016

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well:

Lat _____

Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

COGCC Comments

Comment	User	Date
Remove pieces of liner and netting that are mixed in the soil on the SW section of the pad.	lujanc	09/23/2016

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
671000446	Encana K22 W pad. Tank Battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3960820
671000447	Encana K22 W pad. Secondary Containment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3960821
671000448	Encana K22 W pad. Trash	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3960822