

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/20/2016

Submitted Date:

09/23/2016

Document Number:

671000449**FIELD INSPECTION FORM**Loc ID 335909 Inspector Name: LUJAN, CARLOS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|-------|----------------------------|--------------------------------|
| Spencer, Stan | | stan.spencer@state.co.us | EPS, NW Region |
| Rider, Lindsey | | Lindsey.Rider@encana.com | Manager, Field Environmental |
| Lujan, Carlos | | carlos.lujan@state.co.us | EPS, NW Region |
| Middleton, Brett | | Brett.Middleton@encana.com | Environmental Specialist |
| Fischer, Alex | | alex.fischer@state.co.us | Environmental Supervisor, NW |
| Ramos, Martha | | martha.ramos@state.co.us | Financial Assurance Supervisor |

General Comment:

Environmental Inspection conducted to document that no open pits remain on site. On Site with Brett Middleton from Encana. Equipment on site include a 300 bbl produced/condensate tank, separators and active wells. Two sand traps were observed near the well heads. No indication of pits were observed on site. Pit Facility #414392 has been closed in accordance with REM #9273 and Centralized Facility #441578 was not constructed.

No junk, staining or weeds were observed onsite. Good housekeeping. Sign by wellhead.

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

COGCC Comments

| Comment | User | Date |
|------------------------------|--------|------------|
| No pits on site. See photos. | Iujanc | 09/23/2016 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------------------------|---|
| 671000449 | INSPECTION APPROVED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3960996 |
| 671000450 | Encana A05 - Wellheads and Sand Traps | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3960989 |
| 671000451 | Encana A05 - Footprint of former pit | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3960990 |
| 671000452 | Encana A05 - No Pits | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3960991 |