

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/22/2016

Submitted Date:

09/26/2016

Document Number:

674602820**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
321359 _____ Maclaren, Joe _____ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10575Name of Operator: 8 NORTH LLCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Canfield, Chris		chris.canfield@state.co.us	
Carlisle, Josh		jcarlisle@extractionog.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Hazard, Ellice		ellice.hazard@state.co.us	
,		COGCCInspections@extracti onog.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206768	WELL	PR	07/11/1994	GW	013-06263	BRERETON 2-14	EG

General Comment:

COGCC Integrity Inspection performed on September 22nd, 2016 in response to initial form 19 spill report Doc #401102670 received on 09/01/2016 that states the following: During equipment replacement hydrocarbon impacted soil were encountered. No groundwater was encountered in the excavation. Further excavation will be completed to delineate the extent of impacted material, including confirmation soil sampling. The equipment/ flowline section of this report outlines details of information obtained during this field inspection. Photo's uploaded can be accessed via link(s) at end of report.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Flow Line

#

Comment: As outlined on supplemental form 19 doc#401107465 received bt COGCC on 09/12/2016; Abandoned flowlines have been removed. The dumplines will be replaced and pressure tested prior to being put into service. This was confirmed (in process) during this field inspection. (4) Flowlines are scheduled to be replaced including the Produced Water and Crude Oil dump, ECD and Bypass flowlines. Integrity Inspector met with 8 North LLC Contract personnel (TRRSI) while on location. Cleanup/ remediation and construction activities are in progress. Historic abandoned flowline encountered (yellowjacket) has been removed.

Corrective Action: Date: **Venting:**

Yes/No

Comment: Corrective Action: Date: **Flaring:**

Type

Comment: Corrective Action: Date:

Inspected FacilitiesFacility ID: 206768 Type: WELL API Number: 013-06263 Status: PR Insp. Status: EG**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674602821	Flowline removal/ cleanup in progress	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962009
674602822	Excavation/ contruction activity near meter run	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962010
674602823	Excvation/ soils removal at produced water vault	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962011