



**Photo#1:** Overview of Location to NW. Arrow indicates Risers/Gas lines at NW side of Site.

September 10, 2016

Inspection Photos: PRAW API#081-07088



**Photo#2:** View to SW at Cut Slope. Area circled, running through center of Location is well revegetated

September 10, 2016

Inspection Photos: PRAW API#081-07088





**Photo#3:** Fill slope is Weed infested

September 10, 2016

Inspection Photos: PRAW API#081-07088





**Photo#4:** Ground Conditions on Flat.

September 10, 2016

Inspection Photos: PRAW API#081-07088





**Photo#5:** Risers/ lines remain on Location.

September 10, 2016

Inspection Photos: PRAW API#081-07088





**Photo#6:** Guy Anchors remain.

September 10, 2016

Inspection Photos: PRAW API#081-07088



Photos 7 & 8: BMPs remain on Perimeter



September 10, 2016

Inspection Photos: PRAW API#081-07088



Photos 9 & 10: Debris remains on Location.



September 10, 2016

Inspection Photos: PRAW API#081-07088



Photos 11 & 12: Access Road Leading out of Location **.7** Miles to Gate



September 10, 2016

Inspection Photos: PRAW API#081-07088