

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/13/2016

Submitted Date:

10/17/2016

Document Number:

685100083

FIELD INSPECTION FORM

Loc ID 312771 Inspector Name: NEIDEL, KRIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10428
 Name of Operator: DIVERSIFIED ENERGY LLC
 Address: 10940 S PARKER ROAD
 City: PARKER State: CO Zip: 80134

Findings:

- 1 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Haack, Jason		jhaack@oagproduction.com	
Beckstrom, David		david.beckstrom@state.co.us	
Gowen, Peter		peter.gowen@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222309	WELL	PR	11/01/2014	OW	081-05284	A.P. URIE 1	EI
442574	SPILL OR RELEASE	CL	07/21/2015		-	SPILL/RELEASE POINT	EI

General Comment:

On October 13, 2016 COGCC Environmental Staff (Kris Neidel) conducted an environmental field inspection of DIVERSIFIED ENERGY LLC (Diversified) Urie 1 Location ID: 312771. The INSP included Pit Facility 116613, the well (API 05-081-05284), and former tank battery area. Weather was 65 degrees. Well was not producing at time of inspection, electrical disconnect box was double locked. For the most recent Field and Environmental Field inspection report of this facility, please refer to document #673403543. At the time of the inspection, corrective actions (CAs) provided in that inspection had not been addressed. The overall inspection status shall remain the same as that document until all CAs have been completed. The following is a summary: Well head: Valve at well was in lock out position, the flowline off the wellhead terminated to the pad, not blinded, open to atmosphere. Tank Battery: Tanks no longer present as indicated in Inspection Document Number 673403543. Two (2) app 6' dia concrete pads present. Vegetation (weeds) throughout. Electrical panels, electrical conduit, pipe risers, and valves present. Flow lines present west of the pad in the area of concrete pads. Pit Facility ID 116113: No indication of a pit was observed.

Inspected Facilities

Facility ID: 222309 Type: WELL API Number: 081-05284 Status: PR Insp. Status: EI

Facility ID: 442574 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685100084	picture	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3978403