

Construction Inspection



Photo 1. Photo taken from eastern location, facing East, towards topsoil stockpile.

Construction Inspection



Photo 2. Photo taken from the eastern topsoil pile, facing South. Ditch and berm constructed around outer perimeter of topsoil pile.

Construction Inspection



Photo 3. Photo taken from the western soil pile, facing South. Ditch and berm constructed around outer perimeter of subsoil pile. Contractor will re-cut ditch to a wider and deeper depth.

Construction Inspection



Photo 4. Photo taken from center of location, facing South. Water truck on location to control fugitive dust from operations.