

Final Reclamation Inspection- Overview



Aerial imagery taken 2011 using COGCC GISOnline, illustrating well location and tank battery location. Well location meets Rule 1004 standards; however, concrete slab and vault need to be removed from tank battery location.

Final Reclamation Inspection



Photo 1. Photo taken from center of location, facing West. No evidence of disturbance. Location appears to be reflective of reference areas.

Final Reclamation Inspection



Photo 2. Photo taken from center of location, facing North. No evidence of disturbance. Location appears to be reflective of reference areas.

Final Reclamation Inspection



Photo 3. Photo taken from center of location, facing East. No evidence of disturbance. Location appears to be reflective of reference areas.

Final Reclamation Inspection



Photo 4. Photo taken from center of location, facing South. No evidence of disturbance. Location appears to be reflective of reference areas.

Final Reclamation Inspection



Photo 5. Reference photo taken south of location, facing South. Location appears to be reflective of reference areas.

Final Reclamation Inspection



Photo 6. Photo taken from tank battery location. Concrete vault needs to be removed per Rule 1004.

Final Reclamation Inspection



Photo 7. Photo taken from tank battery location. Concrete slab needs to be removed per Rule 1004.