



Photo#1: Overview of Location to NW. Red Bracket shows failed Vegetation area.



Photo#2: View to SW of erosion commencing in Failed Vegetation area.

October 18, 2016

Inspection Photos: Encana PA O`Connell API#045-09353



Photo#3: View of SW Path, channeling, pooling, & channeling again to drain into Access Road BMPs.

October 18, 2016

Inspection Photos: Encana PA O`Connell API#045-09353