

# Final Reclamation Inspection



**Photo 1.** Photo taken from east of location, facing West. Landowner is currently using the location for a cattle staging area.



# Final Reclamation Inspection



**Photo 2.** Photo taken from northern access road, facing South. Landowner is currently using the location for a cattle staging area.