

Final Reclamation Inspection



Photo 1. Photo taken from center of location, facing West. No evidence of disturbance. Uniform vegetative growth throughout location. Active prairie dog town near location.

Final Reclamation Inspection



Photo 2. Photo taken from center of location, facing North. No evidence of disturbance. Uniform vegetative growth throughout location. Active prairie dog town near location.

Final Reclamation Inspection



Photo 3. Photo taken from center of location, facing East. No evidence of disturbance. Uniform vegetative growth throughout location. Active prairie dog town near location.

Final Reclamation Inspection



Photo 4. Photo taken from center of location, facing South. No evidence of disturbance. Uniform vegetative growth throughout location. Active prairie dog town near location.

Final Reclamation Inspection



Photo 5. Reference photo taken North of location, facing West. Location appears to be reflective of reference areas. Active prairie dog town near location.