

Interim Reclamation Inspection



Photo 1. Photo taken from the eastern topsoil stockpile, facing West. Topsoil stockpile was mowed but undesirable weed species are growing on topsoil stockpile.

Interim Reclamation Inspection



Photo 2. Photo taken from the eastern location, facing South. Perimeter was mowed up to the first stormwater ditch but the second stormwater ditch was not mowed.