



photo 1: Facing south along the access road toward the location. The brown vegetation in center of the road is undesirable weed growth.



photo 2: Areas along the access road seemed to have soil compaction issues.



photo 3: Facing south along the access road toward the location. The brown vegetation in center of the road is undesirable weed growth.



photo 4: Facing south toward the location. The round bales remain at the location.



photo 5: The round bale debris remains at the location.



photo 6: South side of the location facing north.



photo 7: West side of the location facing east.



photo 8: There are areas at the location which seem to have compacted soils.