

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/21/2016

Submitted Date:

10/21/2016

Document Number:

679400091**FIELD INSPECTION FORM**
 Loc ID 319960 Inspector Name: CHESSON, BOB On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1801 BROADWAY #500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	DB shows well as PR - Well PA
Montoya, John		john.montoya@state.co.us	
Precup, Jim		james.precup@state.co.us	
Axelsson, John		john.axelsson@state.co.us	
Donato, Scot	(303) 398-0537	sdonato@gwgco.com	Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202005	WELL	PR	10/14/2011	GW	001-07409	ANTELOPE FARMS 1	PA
442383	SPILL OR RELEASE	CL	07/08/2015		-	SPILL/RELEASE POINT	CL

**General Comment:**

Location has been P&A'd. All tank battery equipment and tanks have been removed. Former pits/vault, etc were properly removed and sites closed under spill #400864862 (spill release location/point 442383).

Location is weedy (see photos)

KMG Gathering pipeline riser complex on location and is in good condition.

Photos attached.

**Inspected Facilities**

Facility ID: 202005	Type: WELL	API Number: 001-07409	Status: PR	Insp. Status: PA
Facility ID: 442383	Type: SPILL OR	API Number: -	Status: CL	Insp. Status: CL

**COGCC Comments**

Comment	User	Date
Location has been P&A'd. All tank battery equipment and tanks have been removed. DB shows as PR status. Former pits/vault, etc were properly removed and sites closed under spill #400864862 (spill release location/point 442383).	chessonr	10/21/2016
Location is weedy (see photos)		
KMG Gathering pipeline riser complex on location and is in good condition.		
Photos attached.		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679400091	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3986744">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3986744</a>
679400092	Location looking north - note weeds	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982702">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982702</a>
679400093	Location looking north	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982704">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982704</a>
679400094	Gathering pipeline facility	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982709">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982709</a>
679400095	Gathering pipeline facility	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982710">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982710</a>
679400096	Location looking south - note weeds	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982711">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982711</a>
679400097	Location surface	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982712">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982712</a>
679400098	Location surface	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982713">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982713</a>