



Photo#1: Overview of Location to South.

October 27, 2016

Inspection Photos: Vanguard Dixon Federal Loc#425891



Photo#2: View of Interim Vegetation on North Berm facing East.

October 27, 2016

Inspection Photos: Vanguard Dixon Federal Loc#425891



Photo#3: Eight Wells on Location have been P&A'd; Insert; view of Plated welded on Cut off Casing.

October 27, 2016

Inspection Photos: Vanguard Dixon Federal Loc#425891



Photo#4: Vegetation on Fill Slope at South end of Location is Sparse..

October 27, 2016

Inspection Photos: Vanguard Dixon Federal Loc#425891



Photo#5: View along Cut slope at East Side of Location to South.

October 27, 2016

Inspection Photos: Vanguard Dixon Federal Loc#425891



Photo#6: Rill Erosion is occurring on Cut Slope.

October 27, 2016

Inspection Photos: Vanguard Dixon Federal Loc#425891



Photo#7: View of Reference Area Vegetation.

October 27, 2016

Inspection Photos: Vanguard Dixon Federal Loc#425891