

Interim Reclamation Inspection- Overview



Aerial imagery taken September 2015 using COGCC GISOnline database, illustrating KPK and Kerr McGee shared tank battery location in relation to a corrective action to fix a portion of the access road that was widened by an operator.

Interim Reclamation Inspection



Photo 1. Photo taken west of the batteries, facing North. Corrective actions to repair ruts have been performed.

Interim Reclamation Inspection



Photo 2. Photo taken west of the batteries, facing South. Corrective actions to repair ruts have been performed.

Interim Reclamation Inspection



Photo 3. Photo taken north of the shared tank battery location, facing North along the access road. Need to repair access road that was widened by an operator and re-seed any portions that are disturbed during this process.