

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/28/2016

Submitted Date:

10/31/2016

Document Number:

674602920

### FIELD INSPECTION FORM

Loc ID 423033 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10439  
 Name of Operator: CARRIZO NIOBRARA LLC  
 Address: 500 DALLAS STREET #2300  
 City: HOUSTON State: TX Zip: 77002

**Findings:**

- 2 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Schneider, Jeff	970-867-9437/ (214) 244-3819	jeff@schneiderenergy.com	
Hazard, Ellice		ellice.hazard@state.co.us	
Lowery, Sheldon	713-358-6492	sheldon.lowery@crzo.net	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Johansson, Eric	713-358-6227	eric.johansson@crzo.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
423029	WELL	PR	10/13/2011	OW	087-08161	Wickstrom 5-44-5-60	EG

**General Comment:**

COGCC Integrity Inspector met with Carrizo Oil and Gas Production Foreman Bryce Jess (along with contract personnel) and witnessed annual pressure testing conducted on the flowlines associated with this well. Details in the flowline section of this report.

**Inspected Facilities**

Facility ID: 423029 Type: WELL API Number: 087-08161 Status: PR Insp. Status: EG

**Flowline**

#1	Type:	4 of Lines	
----	-------	------------	--

Flowline Description

Flowline Type: \_\_\_\_\_ Size: \_\_\_\_\_ Material: \_\_\_\_\_  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

Integrity Summary

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_  
 Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: Yes Test Result: Pass Charted: Yes

COGCC Rules(check all that apply)

1101. Installation and Reclamation     1102. Operations, Maintenance, and Repair     1103. Abandonment

Comment: Pressure testing witnessed on the following: Well site (wellhead to separator), oil dump, produced water dump and gas sales flowlines. All tests witnessed are deemed passing/satisfactory. (4) individual flowline pressure tests were completed. Note: The well site flowline was hydrotested / data logger (Crystal Gauge) used to record each pressure test - records retained by Carrizo.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_