



**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:			
Corrective Action:			Date:

**Emergency Contact Number:**

Comment:			
Corrective Action:			Date: _____

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Fencing/:**

	Type WELLHEAD		
Comment:	AG PANEL		
Corrective Action:			Date:

**Equipment:**

					corrective date
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:					Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
			CENTRALIZED BATTERY		
Comment:					
Corrective Action:					Date:

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 266082 Type: WELL API Number: 123-21321 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Comment: PLUMBED TO SURFACE

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<a href="#">CORRECTIVE ACTIONS FROM PREVIOUS INSPECTION DOC#673803736 HAVE BEEN COMPLETED TO COMPLY WITH COGCC RULES</a>	gomezj	10/25/2016

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
672500065	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3989065">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3989065</a>