



Photo 1. View of the project area from the western edge facing eastward.



Photo 2. View of the southeastern portion of the project area from the northwestern edge facing southeastward. Revegetation is progressing with perennial species such as smooth brome (*Bromus inermis*), crested wheatgrass (*Agropyron cristatum*), and rubber rabbitbrush (*Chrysothamnus nauseosus*)



Photo 3. View of the western portion of the project area from the northwestern edge facing southward.



Photo 4. View of area where stormwater flows enter culvert and it appears sediment is carried with it.



Photo 5. View of the outlet from the culvert shown in Photo 4, where it appears sediment debris from the culvert is being discharged outside of the project area and damaging vegetation.