

Construction and Stormwater Inspection



Photo 1. Photo taken from northeastern corner of perimeter, facing West. Sediment trap installed which will be stabilized per the contractor. Topsoil pile stored along northern location. Ditch and berm constructed around outer perimeter of the location.

Construction and Stormwater Inspection



Photo 2. Photo taken from northeastern corner of perimeter, facing South. Ditch and berm constructed around outer perimeter of the location.

Construction and Stormwater Inspection



Photo 3. Photo taken from eastern perimeter of the location, facing South. Sediment trap installed which will be stabilized per the contractor. Ditch and berm constructed around outer perimeter of the location.

Construction and Stormwater Inspection



Photo 4. Photo taken from southwestern corner of perimeter, facing East. Ditch and berm constructed around outer perimeter of the location.

Construction and Stormwater Inspection



Photo 5. Photo taken from southwestern corner of perimeter, facing North. Ditch and berm constructed around outer perimeter of the location.

Construction and Stormwater Inspection



Photo 6. Photo taken from northern location, facing North, toward topsoil pile.