

## Construction and Stormwater Inspection



**Photo 1.** Photo taken from northern perimeter of location, facing West. Topsoil salvage IN-PROCESS and being stored along northern location. Ditch and berm constructed around outer perimeter of the location.

## Construction and Stormwater Inspection



**Photo 2.** Photo taken from eastern perimeter of location, facing South. Ditch and berm constructed around outer perimeter of the location.

# Construction and Stormwater Inspection



**Photo 3.** Photo taken from eastern perimeter of location, facing West. Topsoil salvage IN-PROCESS.

# Construction and Stormwater Inspection



**Photo 4.** Photo taken from southern perimeter of location, facing West. Ditch and berm constructed around outer perimeter of the location.

## Construction and Stormwater Inspection



**Photo 5.** Photo taken from western perimeter of location, facing North. Ditch and berm constructed around outer perimeter of the location.