

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
10/25/2016  
Submitted Date:  
10/26/2016  
Document Number:  
678300570

**FIELD INSPECTION FORM**

Loc ID 327368 Inspector Name: GINTAUTAS, PETER On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10311  
Name of Operator: SYNERGY RESOURCES CORPORATION  
Address: 20203 HIGHWAY 60  
City: PLATTEVILLE State: CO Zip: 80651

**Findings:**

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

| Contact Name      | Phone | Email                    | Comment                                 |
|-------------------|-------|--------------------------|---|
| Pennington, David |       | dpennington@syrginfo.com | <a href="#">All Synergy Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type         | Status | Status Date | Well Class | API Num   | Facility Name         | Insp Status |
|-------------|--------------|--------|-------------|------------|-----------|-----------------------|-------------|
| 246776      | WELL         | PR     | 03/01/2015  | GW         | 123-14573 | WOLFSON 26-1          | EI          |
| 446347      | TANK BATTERY | AC     | 06/27/2016  |            | -         | WOFLSON-64N67W 26NENE | EI          |

**General Comment:**

[well has been plugged and battery removed. Remediation 9796 approved with COA for PBV water vesel removal.](#)

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |  |  |                  |
|--------------------|--|--|------------------|
| Type               | TRASH  |  |                  |
| Comment:           | trash including wood and plastic sheeting at site                                  |  |                  |
| Corrective Action: | Comply with Rule 603.f using the Rule 603.f guidance document for further details. |  | Date: 11/07/2016 |

Overall Good:

**Spills:**

| Type | Area | Volume |  |
|------|------|--------|--|
|      |      |        |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

|                     |  |  |                  |
|---------------------|--|--|------------------|
| Type: Gas Meter Run | # 1  |  | corrective date  |
| Comment:            | shed and meter on location and apparently not needed as well plugged |  |                  |
| Corrective Action:  | remove as part of interim and final reclamation or show why needed   |  | Date: 04/26/2017 |

**Venting:**

|                    |  |       |
|--------------------|--|-------|
| Yes/No             |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 246776 Type: WELL API Number: 123-14573 Status: PR Insp. Status: EI

Facility ID: 446347 Type: TANK API Number: - Status: AC Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description         | URL   |
|--------------|---------------------|---|
| 678300570    | INSPECTION APPROVED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3990675">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3990675</a> |
| 678300571    | shed                | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3984951">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3984951</a> |
| 678300572    | trash               | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3984952">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3984952</a> |