

Inspected Facilities

Facility ID: 295293 Type: WELL API Number: 057-06466 Status: XX Insp. Status: WK

Workover

Comment: Workover on location rigging up for acid job 10/27/2016 and MIT 10/28/2016 as part of process to turn well into UIC.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 673403803 | INSPECTION APPROVED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3990645 |