

Final Reclamation Overview- Summary of corrective actions



Google Earth aerial imagery taken 10/9/2015 illustrating area of interest. The access road, starting from Culvert #1 to the well location and the well location itself, has a Colorado List B noxious weed that needs to be controlled. In addition, erosion needs to be controlled around the drainage by Culvert #1 once the culvert has been removed. Culverts #1 and #2 shall be removed from the access road. Refer to the following photos taken on 9/8/16 for more information.

Final Reclamation Inspection



Photo 1. Photo taken of well sign at approximate center of well location.

Final Reclamation Inspection




Photo 2. Photo taken from approximate center of location, facing West. Perennial vegetation has established at location but the location is inundated with a Colorado List B noxious weed, Diffuse knapweed (*Centaurea diffusa*).

Final Reclamation Inspection



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo 3. Photo taken from approximate center of location, facing North. Perennial vegetation has established at location but the location is inundated with a Colorado List B noxious weed, Diffuse knapweed (*Centaurea diffusa*).

Final Reclamation Inspection




Photo 4. Photo taken from approximate center of location, facing East. Perennial vegetation has established at location but the location is inundated with a Colorado List B noxious weed, Diffuse knapweed (*Centaurea diffusa*).

Final Reclamation Inspection




Photo 5. Photo taken from approximate center of location, facing South. Perennial vegetation has established at location but the location is inundated with a Colorado List B noxious weed, Diffuse knapweed (*Centaurea diffusa*).

Final Reclamation Inspection



Photo 6. Close-up photo taken of Diffuse knapweed.

Final Reclamation Inspection



Photo 7. Photo taken from Culvert #1, facing East. Culvert needs to be removed to establish natural flows, need to remove gravel used to arm the culvert and reseed with native, perennial vegetation that is representative.

Final Reclamation Inspection



Photo 8. Photo taken from Culvert #1, facing West. Access road needs to be stabilized with native, perennial vegetation to prevent further erosion.

Final Reclamation Inspection



Photo 9. Photo taken of Culvert #2 that remains behind and needs to be removed.

Final Reclamation Inspection



Photo 10. Photo taken along the access road, facing East. Diffuse knapweed and a few individuals of Spotted knapweed were observed throughout the entire access road.