

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2016

Submitted Date:

10/28/2016

Document Number:

674901355**FIELD INSPECTION FORM**
 Loc ID 333603 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num:
Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 10345Name of Operator: WILLIAMS FOUR CORNERS LLCAddress: 188 COUNTY ROAD 4900City: BLOOMFIELD State: NM Zip: 87413**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Webre, Matt	505-632-4442	Matt.Webre@williams.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
444488	SPILL OR RELEASE	CL	04/05/2016		-	Deyhydrator	EI

General Comment:

On October 27, 2016 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Williams Four Corners LLC Facility ID #444488. For the most recent environmental field inspection report for this facility, please refer to document #674900903.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	45 bbl. AST has NFPA placards and labels.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Dehydrator	# 1		corrective date
Comment:	Weeds growing underneath equipment.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.F guidance document for futher details.		Date: 11/07/2016

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	<50 BBLS	STEEL AST		37.144518,-107.889879
Comment:	Expanded metal top.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	45 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Lined earthen berm.			
Corrective Action:				Date:

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spill/Remediation:**Comment: [Environmental inspection of Williams equipment on shared location ID #333603, as a result of remediation project #9630.](#)Corrective
Action:

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
On October 27, 2016 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Williams Four Corners LLC Facility ID #444488. For the most recent environmental field inspection report for this facility, please refer to document #674900903. During this follow up inspection of remediation project #9630, it was noted that weeds are present underneath the dehydrator equipment. No environmental issues were observed during this inspection.	hughesj	10/28/2016

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901355	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3993036
674901356	Williams dehy unit and PW AST.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3987597
674901357	Weeds growing around equipment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3987598
674901358	Drip pan underneath pump.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3987599