

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/27/2016

Submitted Date:

10/28/2016

Document Number:

674901359**FIELD INSPECTION FORM**

Loc ID 333603 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 19160Name of Operator: CONOCO PHILLIPS COMPANYAddress: P O BOX 2197City: HOUSTON State: TX Zip: 77252-**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Busse, Dollie	505-324-6104	dollie.l.busse@conocophillips.com	SW Inspection Reports
Walker, Crystal		Crystal.Walker@conocophillips.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261072	WELL	PR	04/18/2006	GW	067-08517	ANIMAS 36-2	EI
444550	TANK BATTERY	AC	01/04/2016		-	ANIMAS-M34N10W 36NESW	EI

General Comment:

On October 27, 2016 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Conoco Phillips Animas 34-10 #36-2. For the most recent field inspection report for this facility, please refer to document #674900900.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Free standing sign near 300 bbl. AST.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	OTHER		
Comment:	Lube oil leaks on prime mover.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.	Date:	11/04/2016

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	300 BBLS	HEATED STEEL AST		37.155350,-107.889910
Comment:					
Corrective Action:		Date:			

Paint

Inspector Name: Hughes, Jim

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	<u>261072</u>	Type:	<u>WELL</u>	API Number:	<u>067-08517</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>444550</u>	Type:	<u>TANK</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On October 27, 2016 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Conoco Phillips Animas 34-10 #36-2. For the most recent field inspection report for this facility, please refer to document #674900900. During this field inspection, fluids were observed leaking from the prime mover.	hughesj	10/28/2016

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901359	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3993037
674901360	Fluids leaking from prime mover.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3987730
674901361	Lube oil leak on prime mover.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3987731