



Photo#1: View of Location from entry to West.

November 2, 2016

Inspection Photos: Laramie Energy McClung Loc#335048



Photo#2: View of Location to east showing reduced footprint and new Interim Reclamation.

Inspection Photos: Laramie Energy McClung Loc#335048

November 2, 2016



Photo#3: View of Location to South, showing successful germination in new Interim Reclamation areas.

Inspection Photos: Laramie Energy McClung Loc#335048

November 2, 2016



Photo#4: Close up view of ground conditions; overgrazing of first year plants.

Inspection Photos: Laramie Energy McClung Loc#335048

November 2, 2016



Photo#5: Grazing of newly seeded areas is retarding vegetation establishment, exposing soil & rock which will lead to erosion issues.

Inspection Photos: Laramie Energy McClung Loc#335048

November 2, 2016