

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2016

Submitted Date:

11/01/2016

Document Number:

682401429**FIELD INSPECTION FORM**
 Loc ID 444349 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email                         | Comment |
|--------------|-------|-------------------------------|---------|
| Brebis, Chad |       | COGCCinspections@anadarko.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 444346      | WELL | XX     | 12/17/2015  | LO         | 123-42571 | GARFIELD 28N-14HZ | CI          |
| 444347      | WELL | XX     | 12/17/2015  | LO         | 123-42572 | GARFIELD 36N-35HZ | CI          |
| 444348      | WELL | XX     | 12/17/2015  | LO         | 123-42573 | GARFIELD 15C-35HZ | CI          |
| 444351      | WELL | XX     | 12/17/2015  | LO         | 123-42575 | GARFIELD 37N-35HZ | CI          |
| 444352      | WELL | XX     | 12/17/2015  | LO         | 123-42576 | GARFIELD 15N-35HZ | CI          |
| 444355      | WELL | XX     | 12/17/2015  | LO         | 123-42579 | GARFIELD 2N-14HZ  | CI          |
| 444357      | WELL | XX     | 12/17/2015  | LO         | 123-42581 | GARFIELD 27C-14HZ | CI          |

**General Comment:**

This is a construction and stormwater inspection in response to Form 42 Document #401133615.

### Location Construction

Location ID: 444349

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: SATISFACTORY CDP: \_\_\_\_\_

Comment: Topsoil salvage IN-PROCESS

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

#### Form 2A COAs:

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

#### Wildlife BMPs:

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

#### On Site Inspection (305):

##### Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

##### Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

##### LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

##### Summary of Landowner Issues:

\_\_\_\_\_

##### Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

##### Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Inspected Facilities**

|                            |                   |                              |                   |                         |
|----------------------------|-------------------|------------------------------|-------------------|-------------------------|
| Facility ID: <u>444346</u> | Type: <u>WELL</u> | API Number: <u>123-42571</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>444347</u> | Type: <u>WELL</u> | API Number: <u>123-42572</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>444348</u> | Type: <u>WELL</u> | API Number: <u>123-42573</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>444351</u> | Type: <u>WELL</u> | API Number: <u>123-42575</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>444352</u> | Type: <u>WELL</u> | API Number: <u>123-42576</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>444355</u> | Type: <u>WELL</u> | API Number: <u>123-42579</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>444357</u> | Type: <u>WELL</u> | API Number: <u>123-42581</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms            | Pass            |                         |                       |               |                          |         |
| Ditches          | Pass            |                         |                       |               |                          |         |
| Sediment Traps   | In Process      |                         |                       |               |                          |         |

Comment: Ditch and berm BMP installed around the perimeter of the location, and proposed sediment traps will be installed, per the contractor, along the perimeter of the location. Refer to attached photos in Document #682401430.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description         | URL   |
|--------------|---------------------|---|
| 682401429    | INSPECTION APPROVED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3996288">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3996288</a> |
| 682401430    | Location Photos     | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3989980">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3989980</a> |