

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/01/2016

Submitted Date:

11/02/2016

Document Number:

682600226**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 309167 Kosola, Jason 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10084Name of Operator: PIONEER NATURAL RESOURCES USA INCAddress: 5205 N O'CONNOR BLVD STE 200City: IRVING State: TX Zip: 75039**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.co m	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289198	WELL	PR	04/10/2007	GW	071-09192	HOMESTEAD 14-5	EI

General Comment:

This is an environmental inspection to document status of pit and location at time of sampling of produced water going to pit. Sampling conducted in response to COGCC Complaint 200440478. Any corrective actions from previous inspections that have not been addressed are still applicable.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spills/Releases:**

Type of Spill: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: Other _____ Comment: Samples obtained directly from active produced water line

Sample	Sample Type: PRODUCED
Time: 11/01/2016 11:20 (MM/dd/yyyy hh:mm)	GPS: Lat 37.196368 Long -104.808431
BTEX: YES	TPH: _____ Anion: YES Captions: YES General Chemistry: _____
Dissolved Methane: YES	Composition: _____ Stable Isotopes: _____ 8260: YES
8270: YES	RCRA Metals: _____ 910-Metals: YES PAH: _____
Other: _____	
Comment: Samples shipped overnight to ESC Labs in Tennessee.	

Lab:

Lab Name _____

ESC Lab Sciences

COGCC Comments

Comment	User	Date
No environmental issues were identified during inspection. Overall the site was in good condition.	kosolaj	11/02/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682600226	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3997672
682600227	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3991279