

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/09/2016

Submitted Date:

11/09/2016

Document Number:

675203593**FIELD INSPECTION FORM**
 Loc ID 312491 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES, INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Tahmahkera, Kerry	(970) 563-4000	maralextech@gmail.com	All Inspections
Lujan, Carlos		carlos.lujan@state.co.us	
O'Hare, Mickey	(970) 563-4000/ (719) 429-3529	amohare@maralexinc.com	All Inspections
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221769	WELL	PA	01/27/2014	SI	077-08371	USA 1-20 JC	PA

General Comment:

Previous inspection Doc#671000430 on file from 07/22/2016 outlines that "Stockpiled material can be spread out on the pad as a first step prior to final reclamation. Please make sure that all pieces of liner are removed from the stock pile and properly disposed in a landfill." At time of current inspection material was still stacked on location and liner had not been removed. See attached photo.

Inspected FacilitiesFacility ID: 221769 Type: WELL API Number: 077-08371 Status: PA Insp. Status: PA**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203594	Stock pile with liner	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3998319