

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
11/02/2016  
Submitted Date:  
11/02/2016  
Document Number:  
674703292

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: LONGWORTH, MIKE On-Site Inspection   
335674 \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100185  
Name of Operator: ENCANA OIL & GAS (USA) INC  
Address: 370 17TH ST STE 1700  
City: DENVER State: CO Zip: 80202-

**Findings:**

11 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, General	970-285-2665	cogcc.inspections@encana.com	<a href="#">EnCana Inspection email</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
360	WELL	PR	09/20/2008	GW	045-15486	N. PARACHUTE EF12B-DX D31 59	PR
362	WELL	PR	09/21/2008	GW	045-15487	N. PARACHUTE EF11C D31 595	PR
292255	WELL	PR	09/17/2008	GW	045-14664	N. PARACHUTE EF 12A D31 595	PR
292256	WELL	PR	09/17/2008	GW	045-14663	N. PARACHUTE EF11D D31 595	PR
292258	WELL	PR	09/17/2008	GW	045-14665	N.PARACHUTE EF14B D31 595	PR
292259	WELL	PR	09/17/2008	GW	045-14661	N. PARACHUTE EF14A D31 595	PR
292260	WELL	PR	09/18/2008	GW	045-14660	N. PARACHUTE EF12D D31	PR
292261	WELL	PR	09/18/2008	GW	045-14659	N. PARACHUTE EF12C D31 595	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Type: Gas Meter Run	# 16		
Comment:	8 sells and 8 gas lift		
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical containers.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	360	Type:	WELL	API Number:	045-15486	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Gas sampling pod in cellar in response to prior inspection 04/27/2015 doc # 674701328. Update COGCC inspector Mike Longworth of plans and progress of gas leak.								
Corrective Action:				Date:					
Facility ID:	362	Type:	WELL	API Number:	045-15487	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:				Date:					
Facility ID:	292255	Type:	WELL	API Number:	045-14664	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:				Date:					
Facility ID:	292256	Type:	WELL	API Number:	045-14663	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:				Date:					
Facility ID:	292258	Type:	WELL	API Number:	045-14665	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:				Date:					
Facility ID:	292259	Type:	WELL	API Number:	045-14661	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:				Date:					
Facility ID:	292260	Type:	WELL	API Number:	045-14660	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:				Date:					
Facility ID:	292261	Type:	WELL	API Number:	045-14659	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								

Corrective Action:		Date:	
--------------------	--	-------	--

--

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Culverts	Pass			
Compaction	Pass					
Check Dams	Pass					
		Gravel		Material Handling And Spill Prevention	Pass	
Seeding	Pass					
Slope Roughening	Pass					
Gravel	Pass					
Ditches	Pass					
		Compaction	Pass			
Berms	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674703292	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3999038">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3999038</a>