

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/08/2016

Submitted Date:

11/10/2016

Document Number:

673714330**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 322184 Sherman, Susan 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10170Name of Operator: CRIMSON EXPLORATION OPERATING INCAddress: 717 TEXAS AVENUE SUITE 2900City: HOUSTON State: TX Zip: 77002**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|----------------|----------------------|----------------|
| Smith, Ken | (361) 798-6202 | ksmith@crimsonxp.com | Superintendent |
| Stuart, Chet | (432) 302-0538 | cstuart@contango.com | |
| Behrens, Vic | (303) 810-6382 | behrens@netecin.net | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------------|-------------|
| 209601 | WELL | PR | 08/09/1985 | OW | 039-06506 | RMPCO-EVERITT-UPRR 43-19 | PR |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|------------|-------|--|
| Signs/Marker: | | | |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| | | | | |
|-----------------------------|--|-----------------------|------------|------------------|
| Inspected Facilities | | | | |
| Facility ID: 209601 | Type: WELL | API Number: 039-06506 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | PR. Aug 2016 reported to COGCC database. | | | |
| Corrective Action: | | | | Date: |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Rip Rap | Pass | | | | | |
| Check Dams | Pass | | | | | |
| Gravel | Pass | Gravel | Pass | | | |
| Compaction | Pass | Compaction | Pass | Material Handling And Spill Prevention | Pass | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|---|----------|------------|
| All comments from previous inspection addressed. No changes to equipment. | ShermaSe | 11/10/2016 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------------|---|
| 673714382 | Crimson RMPCO- EVERITT-UPRR 43-19 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4000163 |