




Photo#1: Overview of Location from Entry to South.



Photo#2: Interim areas are well Vegetated

November 3, 2016

Inspection Photos: Laramie Gunderson Loc#334494 Interim



Photo#3: Location is Stable and has no Soil migration Concerns.

November 3, 2016

Inspection Photos: Laramie Gunderson Loc#334494 Interim