



Photo 1. View of rock check dams on eastern edge of access that need maintenance.



Photo 2. View of weeds growing around fired equipment that need to be removed.





Photo 3. View of stormwater controls in the eastern portion of the project area. Appears to be functioning at this time.



Photo 4. View of the southeastern portion of the project area. Revegetation is progressing on this slope and diversion is in good condition.





Photo 5. View of stormwater controls in the northeastern portion of the project area in good condition.



Photo 6. View of the northwestern portion of the project area. Revegetation is sparse on the slope. Stormwater erosion is occurring beneath the wattle at the top of the slope. This area needs maintenance and likely further stabilization to prevent further erosional channeling.