

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/07/2016

Submitted Date:

11/07/2016

Document Number:

674004567**FIELD INSPECTION FORM**

Loc ID 336225 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|-------|-------------------------------|---------------------------------|
| , Inspections | | COGCCinspections@Anadarko.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 286207 | WELL | PR | 03/13/2012 | OW | 123-24157 | REYNOLDS 2-24 | PR |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | |
|---------------------------|-------------|
| Emergency Contact Number: | |
| Comment: | |
| Corrective Action: | Date: _____ |

| | | | |
|---------------------------|--|-------|------------|
| Good Housekeeping: | | | |
| Type | DEBRIS | | |
| Comment: | Debris at wellhead | | |
| Corrective Action: | Comply with Rule 603.f using the Rule 603.f guidance document for further details. | Date: | 11/18/2016 |

Overall Good: ☐

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

| | | | |
|--------------------|----------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tanak ID | SE GPS |
|---------------------------------------|---|----------|---------------------|----------|--------|
| | | | CENTRALIZED BATTERY | | , |
| Comment: Shared with API 05-123-24335 | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
|------|----------|---------------------|---------------------|-------------|

| | | | | | |
|------------------------|--|--|--|--|-------------------|
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: <div></div> |
| <u>Venting:</u> | | | | | |
| Yes/No | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: <div></div> |
| <u>Flaring:</u> | | | | | |
| Type | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: <div></div> |

Inspected FacilitiesFacility ID: 286207 Type: WELL API Number: 123-24157 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadComment: Bradenhead plumbed to surface.

Corrective Action:

Date: _____

COGCC Comments

| Comment | User | Date |
|---|----------|------------|
| <u>Routine inspection. Debris at well head.</u> | carlilec | 11/07/2016 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------|---|
| 674004567 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3995551 |
| 674004568 | Wellhead signage. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3995506 |
| 674004569 | Debris around wellhead. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3995507 |