

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2016

Submitted Date:

11/15/2016

Document Number:

674103841**FIELD INSPECTION FORM**

Loc ID 433811	Inspector Name: Rickard, Jeff	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 13 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
------------------	----------------------------------	---	-------------------	--

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
,		Cogcc.inspections@crestonepr.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
433810	WELL	PR	12/02/2014	OW	123-37792	Boyd 3E-19H-M368	PR
433812	WELL	PR	12/02/2014	OW	123-37793	Boyd 3B-19H-M368	PR
433813	WELL	PR	12/02/2014	OW	123-37794	Boyd 3G-19H-M368	PR
433814	WELL	PR	12/02/2014	OW	123-37795	Boyd 3C-19H-M368	PR
433815	WELL	PR	05/05/2015	OW	123-37796	Boyd 3D-19H-M368	PR
433816	WELL	PR	12/02/2014	OW	123-37797	Boyd 3F-19H-M368	PR

**General Comment:**

Inspected Facilities			
Facility ID: 433810	Type: WELL	API Number: 123-37792	Status: PR      Insp. Status: PR
<b><u>Producing Well</u></b>			
Comment: PR			
Corrective Action:		Date:	
<b><u>Complaint</u></b>			
Comment:	Complaint DOC# 200440545. Area resident complained about noise coming from the Crestone location at HWY 66 and County Line Road. OGCC staff was on location on 11/15/16. There was a VRU running on location behind sound walls. A sound survey was run 350 ft from the VRU (the noise source) to the SW of location which was in the direction of the complainant. The sound survey resulted in a LeqA of 47.3db. The A scale noise was evaluated due to traffic on HWY 66, however the 47.3db is in compliance with Rule 803 for battery operations day and night 18A DOC#20440548.		
Corrective Action:		Date:	
<b><u>BradenHead</u></b>			
Comment:	Braden head is exposed at surface.		
Corrective Action:		Date:	
Facility ID: 433812	Type: WELL	API Number: 123-37793	Status: PR      Insp. Status: PR
<b><u>Producing Well</u></b>			
Comment: PR			
Corrective Action:		Date:	
<b><u>BradenHead</u></b>			
Comment:	Braden head is exposed at surface.		
Corrective Action:		Date:	
Facility ID: 433813	Type: WELL	API Number: 123-37794	Status: PR      Insp. Status: PR
<b><u>Producing Well</u></b>			
Comment: PR			
Corrective Action:		Date:	
<b><u>BradenHead</u></b>			
Comment:	Braden head is exposed at surface.		
Corrective Action:		Date:	
Facility ID: 433814	Type: WELL	API Number: 123-37795	Status: PR      Insp. Status: PR
<b><u>Producing Well</u></b>			
Comment: PR			
Corrective Action:		Date:	
<b><u>BradenHead</u></b>			
Comment:	Braden head is exposed at surface.		
Corrective Action:		Date:	

Facility ID:	433815	Type:	WELL	API Number:	123-37796	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [PR](#)

Corrective Action:

Date:

**BradenHead**Comment: [Braden head is exposed at surface.](#)

Corrective Action:

Date: \_\_\_\_\_

Facility ID:	433816	Type:	WELL	API Number:	123-37797	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [PR](#)

Corrective Action:

Date:

**BradenHead**Comment: [Braden head is exposed at surface.](#)

Corrective Action:

Date: \_\_\_\_\_

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: DRY LAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? PassProduction areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: DRY LAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674103842	Sound survey	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4003604">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4003604</a>