



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern portion of the project area from the southeastern corner facing westward.



Photo 3. View of the eastern portion of the project area from the southeastern corner facing northward.



Photo 4. View of musk thistles (*Carduus nutans*) growing within then southeastern portion of the interim reclamation area.



Photo 5. View of erosional channel that is approximately 2 to 3 feet wide and deep forming along the western edge of the project area.



Photo 6. View of tank berm that is no longer functioning.



Photo 7. View of erosion exposing roots from adjacent vegetation within the eastern edge of the well pad cut-slope. Stormwater flows are eroding cut-slopes from stormwater run-on and slopes need to be stabilized.