

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
11/10/2016  
Submitted Date:  
11/10/2016  
Document Number:  
674004592

**FIELD INSPECTION FORM**

Loc ID 331960 Inspector Name: Carlile, Craig On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

5 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

| Contact Name  | Phone | Email                         | Comment                         |
|---------------|-------|-------------------------------|---------------------------------|
| , Inspections |       | COGCCinspections@Anadarko.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 269145      | WELL | PR     | 08/01/2006  | GW         | 123-21630 | HOUSTON P 17-17 | PR          |

**General Comment:**

*(This area is intentionally left blank for general comments.)*

**Location**

Overall Good:

|                      |                 |  |       |
|----------------------|-----------------|--|-------|
| <b>Signs/Marker:</b> |                 |  |       |
| Type                 | DRILLING/RECOMP |  |       |
| Comment:             |                 |  |       |
| Corrective Action:   |                 |  | Date: |

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

Multiple Spills and Releases?

|                    |                              |  |       |
|--------------------|------------------------------|--|-------|
| <b>Fencing/:</b>   |                              |  |       |
| Type               | LOCATION                     |  |       |
| Comment:           | Portable pipe cattle fencing |  |       |
| Corrective Action: |                              |  | Date: |

|                    |  |  |       |
|--------------------|--|--|-------|
| <b>Venting:</b>    |  |  |       |
| Yes/No             |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

|                    |  |  |       |
|--------------------|--|--|-------|
| <b>Flaring:</b>    |  |  |       |
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

**Inspected Facilities**

Facility ID: 269145 Type: WELL API Number: 123-21630 Status: PR Insp. Status: PR

**Cement**

Cement Contractor

Contractor Name: \_\_\_\_\_ Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_ Circulate to Surface: \_\_\_\_\_  
 Cement Fall Back: \_\_\_\_\_ Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): \_\_\_\_\_ Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_ Cement Type: \_\_\_\_\_

Comment: Witnessed:  
Reliance Wire Line cut casing with jet cutter at 770 ft.  
Casing loose and circulation established.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Workover**

Comment: Leed

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

| Comment  | User     | Date       |
|--|----------|------------|
| Routine PA inspection.<br>Company representative on location: Jay Chandler | carlilec | 11/10/2016 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description         | URL   |
|--------------|---------------------|---|
| 674004592    | INSPECTION APPROVED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4005094">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4005094</a> |